






P00_3 / 14.11.2021

Detected deviations (6)



#	1	2	3	4	5	6
ID	P2_0013	P2_0086	P2_0016	P2_0030	P2_0031	P2_0032
Type	IfcStair	IfcFloor	IfcColumn	IfcColumn	IfcColumn	IfcColumn
% of Similarity	91.8 %	63,7 %	95 %	58,3 %	99.8 %	78.2 %
Capture						

Number of inspections so far:


1




2

3

Stairs and floor flatness / 05.11.2021

Detected deviations (3)



#	1	2	3
ID	P2_0013	P2_0014	P2_0086
Type	IfcStair	IfcStair	IfcFloor
% of Similarity	78.9 %	89 %	63,7 %
Capture			

Number of inspections so far:


1

2

3

Facilities 2 / 20.09.2021

Detected deviations (2)



#	1	2
ID	P1_0103	P1_0105
Type	IfcElectric Distribution Board	IfcElectric Distribution Board
% of Similarity	89,7 %	86,1 %
Capture		

Number of inspections so far:

1

2

3